ROCKY FLATS PLANT

EMD OPERATING
PROCEDURES MANUAL
VOL I: FIELD OPERATIONS

Manual No.: New Manual No.:

ew Manual No.: rocedure No.:

Procedure No.: Page:

Effective Date: Organization:

5-21000-OPS-FO

4-11000-ER-OPS-FO Table of Contents, Rev 66

1 of 3

05/26/94 Environmental Management

THIS IS ONE VOLUME OF A SIX VOLUME SET WHICH INCLUDES:

VOLUME I: FIELD OPERATIONS (FO)
VOLUME II: GROUNDWATER (GW)
VOLUME III: GEOTECHNICAL (GT)
VOLUME IV: SURFACE WATER (SW)
VOLUME V: ECOLOGY (EE)
VOLUME VI: AIR (AP)

EG&G SUPERSEDED DOCUMENT

TABLE OF CONTENTS
FOR VOLUME I: FIELD OPERATIONS

Procedure <u>No.</u>	<u>Title</u>	Rev. <u>No.</u>	Effective Date
FO.01	Air Monitoring and Dust Control	2	05/12/92
FO.02	Transmittal of Field QA Records CANCELLED	3	04/15/94
DCN 93.01	Working Base Maps CANCELLED	3	04/15/94
FO.03	General Equipment Decontamination	2	05/12/92
•94-DMR-001021	Section FO.03 Text Addition	2	05/26/94
FO.04	Heavy Equipment Decontamination	2	05/12/92
FO.05	Handling of Purge and Development Water	2	05/12/92
94-DMR-000278	Groundwater Monitoring Modifications	2	02/25/94
FO.06	Handling of Personal Protective Equipment	2	05/12/92
FO.07	Handling of Decontamination Water and Wash Water	2	05/12/92
FO.08	Handling of Drilling Fluids and Cuttings	2	05/12/92
DCN 93.01	Better Consistency of Drum Handling	2`	06/29/93

DOCUMENT CLASSIFICATION REVIEW WAIVER PER R.B. HOFFMAN, CLASSIFICATION OFFICE

JUNE 11, 1901

ROCKY FLATS PLANT

EMD OPERATING PROCEDURES MANUAL VOL I: FIELD OPERATIONS Manual No.: New Manual No.:

5-21000-OPS-FO 4-11000-ER-OPS-FO Table of Contents, Rev 66

Procedure No.:

Page:

2 of 3

Effective Date:

05/26/94

Organization: **Environmental Management**

Procedure No. <u>Title</u>		Rev. <u>No.</u>	Effective <u>Date</u>	
FO.09	Handling of Residual Samples	2	05/12/92	
FO.10	Receiving, Labeling, and Handling Environmental Materials Containers	2	05/12/92	
DCN 93.04 DCN 93.05 DCN 93.06 DCN 93.07 93-DMR-000677 94-DMR-000244 94-DMR-000558	DCN 93.05 Drum Labeling Change DCN 93.06 Drum Sample Numbers DCN 93.07 SVE Sampling Overlap 93-DMR-000677 DMR 94-DMR-000244 Drying Agent Modification		06/23/93 06/29/93 06/29/93 08/18/93 11/01/93 03/14/94 04/15/94	
FO.11	Field Communications	2	05/12/92	
FO.12	Decontamination Facility Operations	2	05/12/92	
FO.13	Containerization, Preserving, Handling and Shipping of Soil and Water Samples	2	05/12/92	
93-DMR-000530 93-DMR-000667 94-DMR-000143	Section FO.13 Modification Section FO.13 Modification Composite Sampling Clarification	2 2 2	11/04/93 11/20/93 02/11/94	
FO.14	Field Data Management	2	05/12/92	
DCN 93.05	Replacement of Form 14 C	2	10/06/93	
FO.15	Photoionization Detectors (PIDs) and Flame Ionization Detectors (FIDs)	2	05/12/92	
FO.16	Field Radiological Measurements	2	05/12/92	
DCN 93.02	LUDLUM/FIDLER Guidance	2	06/29/93	
FO.17	Determining Out-Of-Specification Analytical Results for Environmental Samples		To Be Added	
FO.18	Environmental Sample Radioactivity Content Screening	1	05/12/92	

DOCUMENT MODIFICATION REQUEST (DMR)

Page 1 of 1

							· · · · · · · · · · · · · · · · · · ·			1 age 1	<u> </u>
				ing Instructions. cept Signatures		1. Date 5/23/94		25. DMR. No.	94-DMR-	ळा०२।	Pin 57
2 Existing Document Number/Revision F.O.3, Rev. 2 5-21000 - OPS-FO.3, R.2				3. New Docume Revision	ent Number N/A	[be changed with th	သ		
1		Observ@ser	<u>-21000</u>	-015-FC). 5, Kd						
Originator's Name/Phone/Page/Location Suzanne Berman Smith/8670/D4619/080				General Equip	Document Title General Equipment Decontamination						
6. Document Type of Procedure 7. Document Modification Type (Check only one) 2012 5/23 94 Other New Revision of Intent Change of Nonintent Change						. [94 ge □ Edi	torial Correc	tion □ Cance	ellation		
8. Item	9. Page	10. Step		L		11. Proposed Modifica	ations				
	18	Sec. 5.6.6	Cleaning Proc (PCBs) This procedur 1. Us de 2. Th 3. Us 4. Th 5. Us 6. Th 7. If	re applies when easing a hand held stergent such as phoroughly wipe easing a hand held storoughly wipe easing a hand held	Stainless Steel or Te equipment is cleaned in spray bottle, spray equipment with a disposary bottle, spray equipment, properly disporary bottle, spray equipment, and properly	sable cloth or other suita supprent with tap water. carding cloth.	l, or a solu able mater ater.	tion of tap wa	ter and a non-	phosphate labora	atory
l	,		lification, EJO#,			TOCA U-W-		+:			
Item No.	. 1 - Nec	essary to ir	npiement samp	oling in PCB com	aminated areas with t	ninimal TSCA liquid wa	iste genera	HION.			
					n Block 13, and enter NA in	Blocks 14 and 15. If modification	on is for any	type of change or a	cancellation, organ	nizations are listed in	Block 13,
13. Organiz			ock 14, and dates in Sign (if applicable)							15. Date (if applicable	2)
RPM		Bruce Pet		70	D 1		_			5/23/94	J
FOM		Maria Bro		MAAN TO	120		· · ·			5/Julant	
RE		Richard S	Bauma	11/10/10	O Th					£12519=	7
ΪΗ		Lisa Nelo		Julion J	5 Manuel	DN Malla.				5/25/19/	<u></u>
EQS		Mark Bro		D. June	hengust for	J.M. Melou	$u\alpha$			3 25 1	
FOM				= fifte	and the second					5/25/14 5/25/04	
DOE/R	Nick Demos Kurs D. For N Demos 5/25/94 RFFO Steve Slaten 5/25/94							2.1			
		isor (print/sign	Dance	grown of	Colen					5/25/9	75
). Peterman		Z-102lm	- fa l	30P 5 23	<u>. L. * . ! </u>					
		ne/Page/Locati na/5565/D1070		/ .	18. Cost Center 243	19. Charge Number 989263-00	•	20. Requested Co 5/25/94	impletion Date	21. Effective Date 5	24-4
22. Acceler Yes	ated Review	n	23. ORC Review Not Required	This n	on-intent C	nange was pro-	usyid	as en v	Nent ch	ange to ex	qidi+
31. Respons B.D. Per		er (print, sign,	date)	See lo	DOP	5 23 94	4hi	4ms 1	mocrss.	Ime 5/23/9	14
			<i></i>	7		+	BY	NA		ASSIFICATION	NUCNI
							DAT	EN	Α		

DOCUMENT CLASSIFICATION REVIEW WAIVER PER R.B. HOFFMAN, CLASSIFICATION OFFICE JUNE 11, 1991

GENERAL EQUIPMENT DECONTAMINATION

	EG&G ROCKY FLATS PLANT EMD FIELD PROCEDURES SOP		Manual: Procedure No.: Page:	FO.3, Ro 2 o	5-21000-OPS FO.3, Rev. 2 2 of 18	
Category 2			Effective Date: Organization:	7 15 Environmental Managen		
		5 4 5	Sagrantial Samu	da Battlar (Automotia Somm	lor Pere for Sequential Mode)	12
		5.4.5 5.4.6		` -	oler Base for Sequential Mode) oler Base for Sequential Mode)	12.
		3.4.0	• •	•	nic Compounds Analyses	12
		5.4.7		-	om Composite Container	12
	5.5	CLEA	NING PROCEDU	JRES FOR SAMPLE TUB	ING	12
		5.5.1	Silastic Rubber	Pump Tubing Used in Auto	matic Samplers and Other	
			•			12
		5.5.2	•	•		13
		5.5.3		•		13
		5.5.4	Glass Tubing .			13
	5.6	MISC	ELLANEOUS EQ	UIPMENT CLEANING PI	ROCEDURES	14
		5.6.1	Well Sounders of	r Tapes Used to Measure (Groundwater Levels	14
		5.6.2	Submersible Pur	nps and Hoses Used to Pur	ge Groundwater Wells	14
		5.6.3	Field Analytical	Equipment and Other Field	Instrumentation	15
		5.6.4		•• •	• • • • • • • • • • • • • • • • • • • •	16
		5.6.5		•	ted Drums	16
		5.6.6	-	ures for Small Stainless Stee		
			Used to Sample	Media Possibly Containing	PCBs	18
6.0	QUAL	ITY AS	SURANCE/QUA	LITY CONTROL		18
	6.1	EQUI	PMENT RINSE S	AMPLES		18A
7.0	DOCU	MENT	ATION			18A
			LIS	OF EFFECTIVE PAGES		
	Pages			Effective Date	Change Number	
	1-2			06/-194 7/15/94 la	94-DMR-001224	
	9-9A			06/ 194 7/15/94 l	ne 94-DMR-001224	
	10			26/ /94- 7/15/94 In	94-DMR-001224	
	18			05/26/94	94-DMR-001021	

TOTAL NUMBER OF PAGES: 21 (including forms)

GENERAL EQUIPMENT DECONTAMINATION

EG&G ROCKY FLATS PLANT	Manual:	5-21000-OPS
EMD FIELD PROCEDURES SOP	Procedure No.:	FO.3, Rev. 2
	Page:	18 of 18
	Effective Date:	05/27/94
Category 2	Organization:	05/27/94 Environmental Management

If verified free of radiological contamination by a Radiological Engineeringapproved contractor Health and Safety Specialist, return the drum to the storage area.

5.6.6 Cleaning Procedures for Small Stainless Steel or Teflon® Equipment Used to Sample Media Possibly Containing Polychlorinated Biphenols (PCBs)

This procedure applies when equipment is cleaned in the field.

- 1. Using a hand held spray bottle, spray equipment with iso-octanol, or a solution of tap water and a non-phosphate laboratory detergent such as pipex or liquinox.
- 2. Thoroughly wipe equipment with a disposable cloth or other suitable material and discard properly.
- 3. Using a hand held spray bottle, spray equipment with tap water.
- 4. Thoroughly wipe equipment, properly discarding cloth.
- 5. Using a hand held spray bottle, spray equipment with distilled water.
- 6. Thoroughly wipe equipment, and properly discarding cloth.
- 7. If the equipment is not to be used immediately after decontamination then the equipment should be wrapped in plastic or aluminum foil.

6.0 QUALITY ASSURANCE/QUALITY CONTROL

Quality Assurance (QA) and Quality Control (QC) activities will be accomplished according to applicable project plans as well as quality requirements presented in this SOP.

This section outlines guidelines for specific quality control procedures to monitor the effectiveness of cleaning procedures given in the attachments.